

VEHICLE INSPECTION REPORT

YP68XWS

Ford Transit 2.0 TDCi 105ps H2 FWD

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 13/11/2018

Year 2018

Mileage 27,569 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0XXXTTGXJB16198

Body Style Panel Van L2

MOT Due 25/09/2025

CAP Clean £7,750.00

CAP Average £6,700.00

CAP Below £5,225.00

Gearbox MANUAL

Gears 6

AD-BLUE, SIDE LOAD DOOR, ROOF RACK

Tyres

NSF

NSR

OSF

OSR


Spare

Features


- Bluetooth connection
- Front electric windows
- Rear parking sensor
- Drivers airbag
- Auxiliary input socket
- Passenger airbag
- Digital radio
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Qtr Panel nsr
Dented
Over 30mm




3: Door nsr
Dented
Over 30mm




4: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



5: Qtr Panel osr
Dented
Over 30mm



6: Door osf
Dented
Over 30mm



7: Door osf
Dented
Over 30mm



8:



Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		