

VEHICLE INSPECTION REPORT

DG670PK

Man TGS 26.320

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date	19/12/2017	Colour	BLUE	Cab Type	DAY CAB
Year	2017	VIN	WMA18SZZ8JM760622	Gearbox	MANUAL
Mileage	236,308 Km Warranted	Body Style	Dropside & Crane	Axle Combi	6x2
Fuel Type	DIESEL	MOT Due	31/01/2027	Rear Suspension	Air

REAR-LIFT, HMF 1420K (2 EXT) (YEAR 2017) REMOTE CRANE, KINSHOFER BRICK GRAB

Tyres





NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Park assist camera
- Radio/CD


Photos







Condition Check



Damage Photos



1: Seat Base Cover osf
Torn
Over 3mm



2: Door Moulding osf
Scuffed (Unpainted)
Over 100mm



3: Bonnet
Chipped
1 To 5

4: Wing osf
Chipped
Multiple Chips



5: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

6: Door osf
Scratched
Over 25mm Thru Paint



7: Qtr Panel osr
Dented
With Paint Damage

8: Tailgate
Rusted
Over 5mm



9: Qtr Panel nsr
Dented
With Paint Damage

10: Door Moulding nsf
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Turbo Boosting	OK		Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK		No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK
Roof / sunroof	OK		Radio	OK
Windows	OK		Steering	OK