

VEHICLE INSPECTION REPORT

YN16ODF

Ford Transit Custom 270 2.2 TDCI 100PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 01/03/2016

Year 2016

Mileage 97,252 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0YXXTTGYGB58390

Body Style Panel Van L1

MOT Due 14/04/2026

CAP Clean £3,675.00

CAP Average £3,025.00

CAP Below £2,200.00

Gearbox MANUAL

Gears 6

AD-BLUE, SIDE LOAD DOOR

Tyres

NSF

NSR

OSF

OSR





Spare

Features

- Bluetooth connection
- Drivers airbag
- Auxiliary input socket
- Passenger airbag
- Digital radio
- Central locking
- Front electric windows
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bonnet
Dented
Over 30mm




3: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint

4: Door Moulding nsf
Missing
Replace



5: Qtr Panel nsr
Dented
Over 30mm

6: Qtr Panel nsr
Dented
With Paint Damage



7: Door nsr
Scratched
Over 25mm Thru Paint

8: Door osr
Scratched
Over 25mm Thru Paint



9: Qtr Panel osr
Dented
Over 30mm

10: Door osf
Dented
With Paint Damage



11: Wheel osf
Scratched
Over 50mm

12: Seat Base Cover osf
Soiled
Heavy



13: Seat Base Cover nsf
Holed
Over 3mm

14: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		