

VEHICLE INSPECTION REPORT

YT68ULX

Ford Transit Custom 300 2.0 TDCi 105PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 28/09/2018

Year 2018

Mileage 53,076 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0YXXTTGYJT78241

Body Style Panel Van L1

MOT Due 26/07/2025

Gearbox MANUAL

Gears 6

AD-BLUE, SIDE LOAD DOOR, ROOF RACK

Tyres

NSF

NSR

OSF

OSR


Spare

Features


- Bluetooth connection
- Drivers airbag
- Rear parking sensor
- Passenger airbag
- Digital radio
- Central locking
- Front electric windows
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Qtr Panel nsr
Dented
With Paint Damage



4: Qtr Panel nsr
Dented
With Paint Damage



5: Seat Back Cover nsf
Soiled
Heavy

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		