

## VEHICLE INSPECTION REPORT

**YB64ADO**

### Renault Kangoo Maxi ENERGY 1.5 DCI ECO 90PS

#### Inspection

Serious Damage? No

#### Vehicle

VAT Plus VAT

V5 To Follow

#### Details

Reg. date 14/01/2015

Year 2015

Mileage 39,313 Miles  
Warranted

Fuel Type Diesel

Colour WHITE

VIN VF1FW58H552141548

Body Style Panel Van LWB

MOT Due Expired

CAP Clean £2,500.00

CAP Average £2,075.00

CAP Below £1,475.00

Gearbox MANUAL

Gears 5

TWIN SIDE LOAD DOOR, ROOF RACK

#### Tyres

NSF

NSR

OSF

OSR

Spare

## Features

- Bluetooth connection
- Central locking
- Front electric windows
- Cloth seat trim
- Drivers airbag
- Passenger airbag


## Photos







## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Wing nsf  
Cracked  
Replace



3: Door osr  
Dented  
Over 30mm



4: Door osr  
Chipped  
Multiple Chips



5: Bumper Rear  
Chipped  
Multiple Chips



6: Wing osf  
Cracked  
Replace



7: Door Pad osf  
Soiled  
Heavy



8: Seat Base Cover osf  
Soiled  
Heavy



9: Seat Base Cover nsf  
Soiled  
Heavy

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
OK		Poor	
Poor		No	
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK