

# VEHICLE INSPECTION REPORT

**DK19VCF**

## ISUZU N75 190

### Inspection

### Vehicle

|     |           |
|-----|-----------|
| VAT | Plus VAT  |
| V5  | To Follow |

### Details

|           |                      |            |                   |                 |            |
|-----------|----------------------|------------|-------------------|-----------------|------------|
| Reg. date | 04/03/2019           | VIN        | JAANPR75MJ7100449 | Axle Combi      | 4x2        |
| Year      | 2019                 | Body Style | Dropside          | Rear Suspension | Steel      |
| Mileage   | 296,531 Km Warranted | MOT Due    | 31/03/2026        | Tail Lift       | Cantilever |
| Fuel Type | Diesel               | Cab Type   | DAY CAB           |                 |            |
| Colour    | BLUE/YELLOW          | Gearbox    | AUTOMATIC         |                 |            |

\*WARNING LIGHT ON DASH\* SERVICE SCHEDULE LIST AVAILABLE, SURROUND CAMERA SYSTEM

### Tyres

|       |
|-------|
| NSF   |
| NSR   |
| OSF   |
| OSR   |
| Spare |

## Features

- Park assist camera