

## VEHICLE INSPECTION REPORT

**NX19YOW**

### Peugeot Expert 1200 1.6 BlueHDi 95PS

#### Inspection

Serious Damage? No

#### Vehicle

VAT Plus VAT

V5 Present

#### Details

Reg. date 20/03/2019

VIN VF3VBBHVBKZ018084

CAP Below £4,025.00

Year 2019

Body Style Panel Van LWB

Gearbox MANUAL

Mileage 64,685 Miles  
Warranted

MOT Due 20/03/2026

Gears 5

Fuel Type Diesel

CAP Clean £5,750.00

Colour WHITE

CAP Average £5,050.00

\*WARNING LIGHT ON DASH\* TWIN SIDE LOAD DOOR, E/ MIRRORS, ROOF RACK

#### Tyres

NSF

NSR

OSF

OSR

Spare

### Features

- Bluetooth connection
- Auxiliary input socket
- Passenger airbag
- Cruise control
- Digital radio
- Central locking
- Park assist camera
- Front electric windows
- Cloth seat trim
- Rear parking sensor
- Drivers airbag


### Photos







## Condition Check



## Damage Photos



1: Panel Front  
Scratched  
UpTo 25mm Not Thru Paint



2: Bonnet  
Chipped  
Multiple Chips



3: Qtr Panel nsr  
Chipped  
Multiple Chips



4: Qtr Panel nsr  
Dented  
Over 30mm



5: Qtr Panel nsr  
Chipped  
Multiple Chips



6: Qtr Panel Moulding os  
Scuffed (Unpainted)  
Over 100mm



7: Qtr Panel osr  
Chipped  
Multiple Chips



8: Door osf  
Chipped  
Multiple Chips



9: Door Pad osf  
Soiled  
Heavy



10: Seat Base Cover osf  
Torn  
Over 3mm



11: Seat Base Cover nsf  
Soiled  
Heavy

**Interior**

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		