

# VEHICLE INSPECTION REPORT

**YF71GYH**

## Maxus Deliver 3 90KW

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date 28/02/2022

Year 2022

Mileage 48,166 Miles Not Warranted

Fuel Type Electric

Colour WHITE

VIN LSH14C4C9MA050622

Body Style Panel Van L1

CAP Clean £6,875.00

CAP Average £6,375.00

CAP Below £5,475.00

Gearbox AUTOMATIC

Gears 1

SIDE LOAD DOOR, E/ MIRRORS

### Tyres

NSF

NSR

OSF

OSR

Spare

## Features

- Bluetooth connection
- Cruise control
- Navigation system
- Park assist camera
- Rear parking sensor
- Digital radio
- USB/iPod interface
- Air conditioning
- Front electric windows
- Drivers airbag
- Central locking
- Cloth seat trim

## Photos










## Condition Check



## Damage Photos



1: Bumper Front  
Chipped  
Over 5mm



2: Bonnet  
Chipped  
Multiple Chips





3: Bonnet  
Chipped  
Multiple Chips



4: Bumper Front  
Scratched  
Over 100mm Thru Paint



5: Bumper Front  
Scratched  
Over 100mm Thru Paint



6: EV Charging Port  
Broken  
Replace



7: Front TowEye Cvr  
Missing  
Replace



8: Door nsr  
Dented  
Over 30mm



9: Seat Base Cover osf  
Soiled  
Light

Interior

Carpet Condition		OK	Upholstery Condition		OK
Seat Condition		Average	Odour		No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Turbo Boosting	OK		Gearbox Static Gear Selection (engine running)	OK	
Parking Brake	OK		No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	
Windows	OK		Radio	OK	
Sat nav	OK		Steering	OK	