

# VEHICLE INSPECTION REPORT

**WV22NRE**

## Maxus Deliver 3 90KW

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date 10/08/2022

Year 2022

Mileage 53,640 Miles Not Warranted

Fuel Type Electric

Colour WHITE

VIN LSH14C4C1NA103959

Body Style Panel Van L1

MOT Due 09/08/2025

CAP Clean £7,200.00

CAP Average £6,675.00

CAP Below £5,725.00

Gearbox AUTOMATIC

Gears 1

SIDE LOAD DOOR, E/ MIRRORS

### Tyres

NSF

NSR

OSF

OSR

Spare


## Features

- Bluetooth connection
- Digital radio
- Drivers airbag
- Cruise control
- USB/iPod interface
- Central locking
- Navigation system
- Air conditioning
- Cloth seat trim
- Rear parking sensor
- Front electric windows

## Photos












## Condition Check



## Damage Photos



1: Seat Base Cover osf  
Soiled  
Light



2: Seat Base Cover nsf  
Soiled  
Light



3: Front TowEye Cvr  
Missing  
Replace



4: EV Charging Port  
Broken  
Replace



5: Door nsf  
Dented  
With Paint Damage



6: Moulding nsf Wing  
Scratched (Painted)  
Over 25mm Thru Paint



7: Bumper Rear Moulding  
Broken  
Replace



8: Panel Rear  
Scratched  
Over 25mm Not Thru Paint

## Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Average	Odour	No
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK