



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PE17HUU

Daf CF 440

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details			
Reg. date	28/03/2017	VIN	XLRTGM4100G151869
Year	2017	Body Style	Tractor Unit
Mileage	1,096,546 Km Warranted	Service history	Yes
Fuel Type	Diesel	MOT Due	30/04/2026
Colour	RED	Cab Type	SLEEPER CAB
		Gearbox	AUTOMATIC
		Axle Combi	6x2
		Steering Combi	Mid-Lift
		Rear Suspension	Air

COLLECTED AS NON-RUNNER, CORROSION



Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Air conditioning


Photos







Condition Check



Damage Photos



1: Wing of
Scratched
Over 25mm Thru Paint



2: Bonnet
Chipped
Multiple Chips



3: Screen Front
Chipped
Over 10mm

4: Wing nsf
Chipped
Multiple Chips



5: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

6: Wing Front Arch Extension os
Scuffed (Unpainted)
Over 100mm



7: Qtr Panel osr
Scratched
Over 25mm Thru Paint

8: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



9: Wing Front Arch Extension os
 Scratched (Painted)
 Over 25mm Thru Paint

10: Door Pad osf
 Torn
 Over 10mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK