



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

WP67JVF

MERCEDES-BENZ SPRINTER 314 CDI

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Buyer To Apply

Details		VIN		CAP Below	
Reg. date	29/12/2017	VIN	WDB9061352N747272	CAP Below	£4,600.00
Year	2017	Body Style	Dropside	Gearbox	MANUAL
Mileage	59,559 Miles Not Warranted	MOT Due	Expired	Gears	6
Fuel Type	Diesel	CAP Clean	£7,425.00		
Colour	WHITE	CAP Average	£6,200.00		

NON-RUNNER, POWERS UP WONT START, CAMBELT SNAPPED


Tyres
NSF
NSR
OSF
OSR
Spare

Features


- Cruise control

Photos





Condition Check



Damage Photos



1: Tailgate Trim Panel
Scratched (Painted)
Over 25mm Thru Paint



2: Wing of
Scratched
Rusted



3: Headlamp ns
Broken
Replace

4: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition	Poor	Upholstery Condition	Average
Seat Condition	Poor	Odour	No
Engine Runs	Fault	Gearbox 1st and Reverse Test	Fault
Brakes	Fault	Clutch Slip Test from Static	Fault
Parking Brake	Fault	Gearbox Static Gear Selection (engine running)	Fault
		No Excessive Smoking	Fault