



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

DK17KXE

Man TGS 26.360

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details			
Reg. date	12/05/2017	VIN	WMA18SZZ7HP083717
Year	2017	Body Style	Dropside & Crane
Mileage	169,688 Km Warranted	MOT Due	31/03/2026
Fuel Type	Diesel	Cab Type	DAY CAB
Colour	BLUE	Gearbox	MANUAL
		Axle Combi	6x2
		Steering Combi	Rear-Lift Steer
		Rear Suspension	Air

SERVICE SCHEDULE LIST AVAILABLE, HMF 1420K REMOTE CRANE (YEAR 2017), SURROUND CAMERA SYSTEM

Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Park assist camera


Photos








Condition Check



Damage Photos



1: Wing of
Scratched
Over 25mm Thru Paint



2: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



3: Screen Front
Cracked
Replace

4: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



5: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

6: Qtr Panel nsr
Dented
With Paint Damage



7: Qtr Panel osr
Dented
With Paint Damage

8: Door osf
Scratched
Up To 25mm Thru Paint



9: Seat Base Cover of
 Holed
 Over 3mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK