

VEHICLE INSPECTION REPORT

FJ72VRL

Mercedes-Benz eVito 85kW 66kWh Progressive

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 10/11/2022

Year 2022

Mileage 30,927 Miles Not Warranted

Fuel Type Electric

Colour WHITE

VIN W1V44760324125971

Body Style Panel Van L2

MOT Due 09/11/2025

CAP Clean £11,000.00

CAP Average £10,150.00

CAP Below £8,750.00

Gearbox AUTOMATIC

CHARGING CABLE IN REAR, HEATED WINDSCREEN, E/MIRRORS, SIDE LOAD DOOR

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Bluetooth connection
- Drivers airbag
- Cruise control
- Passenger airbag
- Park assist camera
- Central locking
- Front electric windows
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Seat Base Cover nsf
Soiled
Heavy



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



4: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

Interior

Carpet Condition -
Seat Condition Poor

Upholstery Condition -
Odour -

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK