



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**PO13DYA**

## Daf LF 45.140

**Non Runner**

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details					
Reg. date	01/04/2013	VIN	XLRAE45FF0L425017	Cab Type	DAY CAB
Year	2013	Body Style	Box Van	Gearbox	MANUAL
Mileage	871,599 Km Warranted	Service history	Yes	Axle Combi	4x2
Fuel Type	Diesel	Service documents	Printout	Rear Suspension	Steel
Colour	RED	MOT Due	Expired		


\*NON-RUNNER, STARTS DOES NOT DRIVE, CLUTCH INOPERABLE, WARNING LIGHTS ON DASH, CAB CORROSION, WIPER MOTOR, TACHOGRAPH, TAIL LIFT RAM NEED ATTENTION\*



Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

## Features


- Radio/CD

## Photos





## Condition Check



## Damage Photos



1: Carpets Front  
Torn  
Over 10mm

2: Bonnet  
Chipped  
Multiple Chips



3: Bumper Front  
Rusted  
Over 5mm

4: Wing of  
Chipped  
Multiple Chips



5: Door of  
Dented  
With Paint Damage

6: Door Moulding of  
Scuffed (Unpainted)  
Over 100mm



7: Qtr Panel of  
Rusted  
Over 5mm

8: Tailgate  
Rusted  
Over 5mm



9: Qtr Panel nsr  
Rusted  
Over 5mm

10: Door nsf  
Dented  
Over 30mm



11: Wing nsf  
Scratched  
Over 25mm Thru Paint

**Interior**

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	Fault
Brakes	OK	Clutch Slip Test from Static	Fault
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	Fault
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	Fault	Service indicator light illuminated	OK

Windows

OK

Radio

OK

Steering

OK