



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

FN17CNK

Daf LF 230

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow

Details

Reg. date	24/07/2017	Fuel Type	Diesel	Body Style	Chassis Cab
Year	2017	Colour	WHITE	MOT Due	31/05/2026
Mileage	381,540 Km Warranted	VIN	XLRAEL3700L466287	Gearbox	AUTOMATIC

WARNING LIGHTS ON DASH

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Radio/CD
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Seat Base Cover nsf
Holed
Over 3mm

2: Seat Base Cover osf
Torn
Over 3mm



3: Centre Console Front
Broken
Replace

4: Bonnet
Chipped
Multiple Chips



5: Moulding nsf Wing
Scratched (Painted)
Up To 25mm Thru Paint

6: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



7: Bumper Front Moulding
Broken
Replace

8: Door nsf
Chipped
Multiple Chips



9: Lamp nsr
Missing
Replace

10: Lamp osr
Broken
Replace



11: Door osf
Chipped
Multiple Chips

12: Moulding osf Wing
Broken
Replace



13: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm

14: Switches And Controls
Missing
Replace

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	Fault
ABS light illuminated	Fault	DPF light illuminated	Fault
		Service indicator light illuminated	Fault