



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

DF19XRD

Isuzu N75 190

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details			
Reg. date	30/07/2019	VIN	JAANPR75MJ7100679
Year	2019	Body Style	Dropside
Mileage	287,995 Km Warranted	MOT Due	31/08/2026
Fuel Type	Diesel	Cab Type	DAY CAB
Colour	BLUE/YELLOW	Gearbox	AUTOMATIC
		Axle Combi	4x2
		Rear Suspension	Steel
		Tail Lift	Cantilever

SERVICE SCHEDULE LIST AVAILABLE, SURROUND CAMERA SYSTEM

Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Park assist camera
- Air conditioning


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bonnet
Dented
Over 2 Up To 10mm



3: Door nsf
Dented
Over 30mm

4: Door nsf
Dented
Between 10mm + 30mm




5: Door Mirror Assy nsf
Broken
Replace

6: Door nsf
Dented
Between 10mm + 30mm



7: Door nsf
Chipped
Edge Chip

8: Qtr Panel nsr
Dented
With Paint Damage



9: Qtr Panel osf
Dented
With Paint Damage

10: Door osf
Chipped
Edge Chip



11: Door osf
Dented
Between 10mm + 30mm

12: Door osf
Dented
Between 10mm + 30mm




13: Door Mirror Assy osf
Broken
Replace

14: Door osf
Dented
With Paint Damage



15: Door osf
Dented
With Paint Damage

16: Carpets Front
Holed
Over 3mm



17: Seat Base Cover osf
Holed
Over 3mm

18: Centre Console Front
Missing
Replace

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK