

VEHICLE INSPECTION REPORT

LC20HFS

Ford Transit 2.0 EcoBlue 130ps Leader

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 03/07/2020

VIN WF0EXXTTREKY79349

CAP Below £5,025.00

Year 2020

Body Style Panel Van L4

Gearbox MANUAL

Mileage 111,100 Miles Not Warranted

MOT Due Expired

Gears 6

CAP Clean £6,875.00

Fuel Type LNG

CAP Average £6,125.00

Colour WHITE

WARNING LIGHT ON DASH, CLUTCH PEDAL LOW AD-BLUE, SIDE LOAD DOOR, DEADLOCKS (WITH KEY)

Tyres

NSF

NSR

OSF

OSR


Spare

Features

- Bluetooth connection
- USB/iPod interface
- Cloth seat trim
- Front parking sensor
- Front electric windows
- Rear parking sensor
- Drivers airbag
- Digital radio
- Central locking


Photos







Condition Check



Damage Photos



1: Door Mirror Assy nsf
Missing
Replace



2: Door Mirror Assy osf
Broken
Replace



3: Roof
Dented
With Paint Damage



4: Door osr
Missing
Replace



5: Other
N/A
N/A

Interior

Carpet Condition	OK	Upholstery Condition	Average
Seat Condition	OK	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK

Windows

OK

Radio

OK

Steering

OK