

VEHICLE INSPECTION REPORT

FX23EBO

Renault Master LL35 ENERGY dCi 145 Business

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 01/06/2023

Year 2023

Mileage 88,665 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN VF1VB000269927116

Body Style Curtainside

MOT Due 31/05/2026

Gearbox MANUAL

Gears 6

Tail Lift Column

WARNING LIGHTS ON DASH AD-BLUE, E/WINDOWS

Tyres

NSF

NSR

OSF

OSR


Spare

Features


- Bluetooth connection
- USB/iPod interface
- Central locking
- Cruise control
- Air conditioning
- Cloth seat trim
- Auxiliary input socket
- Front electric windows
- Digital radio
- Drivers airbag

Photos





Condition Check



Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



2: Door Mirror Assy osf
Broken
Replace

Interior

Carpet Condition OK
Seat Condition OK

Upholstery Condition OK
Odour No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK