



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
 Doncaster
 DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

KX19VDC

Mercedes-Benz Sprinter 314 CDI

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details					
Reg. date	09/05/2019	VIN	WDB9071352N025136	CAP Below	£6,850.00
Year	2019	Body Style	Curtainside	Gearbox	MANUAL
Mileage	194,354 Miles Not Warranted	MOT Due	28/07/2026	Gears	6
Fuel Type	Diesel	CAP Clean	£10,150.00		
Colour	WHITE	CAP Average	£8,700.00		


WARNING LIGHTS ON DASH HEATED WINDSCREEN



Tyres	
NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Screen Front
Chipped
Over 10mm



3: Screen Front
Cracked
Replace

4: Screen Front
Chipped
Up To 10mm



5: Door nsf
Dented
Hail - Moderate

6: Boot Lid
Chipped
Multiple Chips



7: Screen Front
Chipped
Up To 10mm

8: Panel Front
Chipped
Edge Chip



9: Seat Back Cover of
Soiled
Heavy

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	Yes
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK