



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

DK17LBG

Man TGS 26.360

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details					
Reg. date	08/08/2017	Colour	BLUE	Cab Type	DAY CAB
Year	2017	VIN	WMA18SZZ0HM750824	Gearbox	MANUAL
Mileage	280,186 Km Warranted	Body Style	Dropside & Crane	Axle Combi	6x2
Fuel Type	Diesel	MOT Due	31/08/2026	Rear Suspension	Air

HMF 1420K REMOTE CRANE (YEAR 2017), REAR VIEW CAMERA , REAR-LIFT, SERVICE SCHEDULE LIST AVAILABLE


Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Radio/CD


Photos







Condition Check



Damage Photos



1: Door Moulding of
Scuffed (Unpainted)
Over 100mm

2: Bonnet
Chipped
Multiple Chips



3: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

4: Door osf
Dented
Over 30mm



5: Qtr Panel osr
Dented
With Paint Damage

6: Tailgate
Rusted
Over 5mm



7: Qtr Panel nsr
Dented
Over 30mm

8: Door Moulding nsf
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK