



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

MD55TUD

Mercedes-Benz TURAS

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow

Details					
Reg. date	01/06/2017	Colour	GREY	Gearbox	AUTOMATIC
Year	2017	VIN	WDB96702420130374	Axle Combi	4x2
Mileage	153,657 Km Not Warranted	Body Style	Coach	Rear Suspension	Steel
Fuel Type	Diesel	Cab Type	DAY CAB		

5% BUYERS FEE *WARNING LIGHT ON DASH* 27 SEATS PLUS DRIVER, 3PT SEATBELTS, OVERHEAD STOWAGE, REAR EMERGENCY EXIT

Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Park assist camera
- Air conditioning


Photos







Condition Check



Damage Photos



1: Bumper Front
Cracked
UpTo 25mm



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Qtr Panel nsr
Rusted
Over 5mm



5: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

6: Bumper Rear
Scratched
Over 100mm Thru Paint



7: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK