



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PE17HNF

Daf CF 440

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Present

Details

Reg. date	06/03/2017	VIN	XLRTGM4100G148955	Gearbox	AUTOMATIC
Year	2017	Body Style	Tractor Unit	Axle Combi	6x2
Mileage	1,326,315 Km Warranted	Service history	Yes	Steering Combi	Mid-Lift
Fuel Type	Diesel	MOT Due	31/08/2026	Rear Suspension	Air
Colour	RED	Cab Type	SLEEPER CAB		

COLLECTED AS NON-RUNNER, CYLINDER HEAD/INJECTOR PIPES REQUIRE ATTN *WARNING LIGHT ON DASH*

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Air conditioning

Photos





Condition Check



Damage Photos



1: Wing osf
Chipped
Multiple Chips

2: Bumper Front
Chipped
Multiple Chips



3: Fog Lamp Surround os
Broken
Replace

4: Bonnet
Chipped
Multiple Chips



5: Wing nsf
Chipped
Multiple Chips

6: Door nsf
Scratched
Over 25mm Thru Paint



7: Qtr Panel Arch Extension ns
Missing
Replace

8: Qtr Panel Arch Extension os
Missing
Replace



9: Wing Front Arch Extension os
Scratched (Painted)
Over 25mm Thru Paint

10: Door osf
Scratched
Over 25mm Not Thru Paint



11: Centre Console Front
Missing
Replace

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK