


VEHICLE INSPECTION REPORT



MERCEDES-BENZ ACTROS 2546

Inspection	Vehicle		
	VAT	Plus VAT	
	V5	Present	
Details			

Reg. date	28/01/2019	VIN	WDB96342320330761	Axle Combi	6x2
Year	2019	Body Style	Tractor Unit	Steering Combi	Mid-Lift
Mileage	657,067 Km Warranted	MOT Due	31/01/2026	Rear Suspension	Air
Fuel Type	Diesel	Cab Type	STREAMSPACE CAB		
Colour	BLUE		(2.3M, 170MM)		
		Gearbox	AUTOMATIC		

SLIDING 5TH WHEEL

Tyres			
Tyres NSF			
NSR			
OSF			
OSR			
Spare			

Features

Air conditioning

Photos



