



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

WR66VOY

Mitsubishi L200 2.5 134Bhp

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Buyer To Apply

Details			
Reg. date	30/11/2016	Colour	WHITE
Year	2016	VIN	MMCCNKB40FD838057
Mileage	54,463 Miles Not Warranted	Body Style	Pickup Double Cab
Fuel Type	Diesel	MOT Due	09/11/2026
		Gearbox	MANUAL
		Gears	5

Tyres	
NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Radio/CD
- Air conditioning
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
With Paint Damage

2: Wing osf
Rusted
Over 5mm



3: Door osf
Dented
Over 30mm

4: Qtr Panel osr
Dented
With Paint Damage



5: Qtr Panel osr
Dented
Over 30mm

6: Tailgate
Dented
Over 30mm



7: Qtr Panel nsr
Dented
Over 30mm

8: Wing nsf
Dented
With Paint Damage



9: Bumper Front
 Scratched
 25 to 100mm Thru Paint

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK