



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**PN70CWG**

## Daf LF 180

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT  
V5 Present

### Details

Reg. date	12/10/2020	Colour	WHITE	Gearbox	MANUAL
Year	2020	VIN	XLRAEL1500L496383	Axle Combi	4x2
Mileage	256,325 Km Warranted	Body Style	Fridge Box	Rear Suspension	Steel
Fuel Type	Diesel	Cab Type	DAY CAB	Rear Doors	Barn

\*INTERMITTENT WARNING LIGHTS ON DASH\* CARRIER XARIOS 600, STANDBY PLUG

### Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

## Features

- Cruise control
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag
- Digital radio
- Passenger airbag
- LED headlights
- Central locking


## Photos







## Condition Check



## Damage Photos



1: Door osf  
Scratched  
UpTo 25mm Not Thru Paint



2: Door osf  
Chipped  
Multiple Chips



3: Door osf  
 Scratched  
 UpTo 25mm Thru Paint

4: Panel Front  
 Scratched  
 UpTo 25mm Thru Paint



5: Bumper Front  
 Scratched  
 Over 100mm Thru Paint

6: Door osr  
 Scratched  
 UpTo 25mm Not Thru Paint

**Interior**

**Carpet Condition**  
**Seat Condition**

OK  
 OK

**Upholstery Condition**  
**Odour**

OK  
 -

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK

Windows

OK

Radio

OK

Steering

OK