

VEHICLE INSPECTION REPORT

OXZ141

SCANIA 141

Inspection

Vehicle

VAT	Margin
V5	To Follow

Details

Reg. date	05/03/1980	Colour	RED/WHITE	Gearbox	MANUAL
Year	1980	VIN	1029161	Axle Combi	4x2
Mileage	508,553 Km Not Warranted	Body Style	Tractor Unit		
Fuel Type	Diesel	Cab Type	SLEEPER CAB		

LEFT HAND DRIVE, 10 SPEED GEARBOX, BEEN USED FOR REGULAR ROAD RUNS

Tyres

NSF
NSR
OSF
OSR
Spare

Photos

