



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

VN73YBU

Renault Kangoo ML19 1.3 TCe 100PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 27/12/2023

Year 2023

Mileage 32,317 Miles Not Warranted

Fuel Type Petrol

Colour WHITE

VIN VF1RFK00071802617

Body Style Panel Van SWB

MOT Due 26/12/2026

CAP Clean £10,100.00

CAP Average £9,375.00

CAP Below £8,075.00

Gearbox MANUAL

Gears 6

TWIN SIDE LOAD DOOR, APPLE/ANDROID CAR PLAY, E/MIRRORS.

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Rear parking sensor
- Radio/CD
- Air conditioning
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Door osf
Chipped
Over 5mm

2: Bumper Front
Insecure
Action Required



3: Bumper Front
Cracked
Over 25mm

4: Bumper Front
Insecure
Action Required



5: Unclassified
Major Parts Missing
Report Only

6: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



7: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK