



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

VU73DHD

Renault Kangoo ML19 1.3 TCe 100PS

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Buyer To Apply

Details					
Reg. date	27/12/2023	VIN	VF1RFK00371802613	CAP Below	£6,875.00
Year	2023	Body Style	Panel Van SWB	Gearbox	MANUAL
Mileage	62,478 Miles Not Warranted	MOT Due	26/12/2026	Gears	6
Fuel Type	Petrol	CAP Clean	£8,600.00		
Colour	WHITE	CAP Average	£7,975.00		

WARNING LIGHTS ON DASH TWIN SIDE LOAD DOOR, APPLE/ANDROID CAR PLAY, E/MIRRORS.

Tyres
NSF
NSR
OSF
OSR
Spare

Features


- Rear parking sensor
- Radio/CD
- Air conditioning
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Door osf
Dented
Over 2 UpTo 10mm

2: Tailgate
Dented
With Paint Damage

Interior

Carpet Condition -
Seat Condition -

Upholstery Condition -
Odour -

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK