

VEHICLE INSPECTION REPORT

FG19PNE

Renault Master 35 2.3 DCI 130PS Business FWD

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Reg. date	27/03/2019	VIN	VF1VA000260382588	CAP Below	£3,350.00
Year	2019	Body Style	Luton LWB	Gearbox	MANUAL
Mileage	203,717 Miles Not Warranted	MOT Due	Expired	Gears	6
Fuel Type	Diesel	CAP Clean	£4,875.00	Axle Combi	4x2
Colour	WHITE	CAP Average	£4,300.00		

CRACK IN WINDSCREEN AD-BLUE, E/ MIRRORS

Tyres

NSF

NSR

OSF

OSR


Spare

Features


- Bluetooth connection
- Radio/CD
- Front electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Cloth seat trim

Photos





Condition Check




Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front Moulding
Missing
Replace



3: Bumper Front
Scratched
Over 100mm Thru Paint

4: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



5: Qtr Panel nsr
Dented
Over 30mm

6: Qtr Panel nsr
Dented
Over 30mm



7: Qtr Panel osr
Scratched
Over 25mm Thru Paint

8: Qtr Panel osr
Scratched
Over 25mm Thru Paint





9: Qtr Panel osr
Dented
Over 30mm

10: Screen Front
Cracked
Replace



11: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	OK
Seat Condition	Poor

Upholstery Condition	OK
Odour	-