



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

GX19GYO

Ford Ranger WILDTRAK 3.2 TDCI 200PS

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Buyer To Apply

Details			
Reg. date	28/06/2019	VIN	6FPPXXMJ2PJA54239
Year	2019	Body Style	Pickup Double Cab
Mileage	62,745 Miles Not Warranted	MOT Due	14/10/2026
Fuel Type	Diesel	CAP Clean	£13,950.00
Colour	SILVER	CAP Average	£12,050.00
		CAP Below	£9,400.00
		Gearbox	AUTOMATIC
		Gears	6
		Axle Combi	4x4

OUTSTANDING RECALL AD-BLUE, TOW BAR, E/ MIRRORS, HEATED WINDSCREEN

Tyres		
NSF	GENERAL TIRE	OK
NSR	GENERAL TIRE	OK
OSF	GENERAL TIRE	OK
OSR	GENERAL TIRE	OK
Spare		

Features

- Bluetooth connection
- Navigation system
- Cruise control
- Park assist camera
- Front parking sensor
- Heated front seat

Photos






FORD	
Z	e11200746*0154
D	6FPPXAM2PJA64239
E	3270 KG
AQ	6000 KG
C	1480 KG
B	1850 KG
2AB 0.37	



Press OK for km/h
062745.5mils



Condition Check



Damage Photos



1: Bumper Front
Scratched
Over 100mm Thru Paint

2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Bumper Front Moulding
Scratched (Painted)
Over 25mm Thru Paint

4: Wing nsf
Dented
Over 30mm



5: Wheel nsf
Scratched
Over 50mm

6: Wheel nsr
Scratched
Over 50mm



7: Panel Rear
Dented
Over 30mm

8: Tailgate
Dented
Over 30mm



9: Other
N/A
N/A

10: Other
N/A
N/A



11: Bumper Front
Scratched
25 to 100mm Thru Paint

12: Screen Front
Cracked
Replace

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK