



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

KY16SRV

ISUZU D-MAX 2.5 TD

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 31/08/2016

Year 2016

Mileage 111,802 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN MPATFS86JFT030485

Body Style Access Platform

MOT Due 06/06/2026

CAP Clean £5,100.00

CAP Average £4,200.00

CAP Below £3,050.00

Gearbox MANUAL

Gears 6

Axle Combi 4x4

COLLECTED AS NON-RUNNER, ONLY RUNS WITH BOOST PACK, ALTERNATOR SEIZED, PLATFORM REQUIRES ATTENTION, WARNING LIGHTS ON DASH CPL SOCAGE A314 50-0030 PLATFORM (YEAR 2016), V5 NEW KEEPER DOCUMENT REFERENCE NUMBER AVAILABLE FOR TAXATION PURPOSES

Tyres

NSF

NSR

OSF

OSR

Spare

Features

- Auxiliary input socket
- Digital radio
- Air conditioning
- Front electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Hole
Over 25mm



3: Number Plate Front
Broken
Replace

4: Bumper Front
Scratched
Over 100mm Thru Paint



5: Wing nsf
Dented
With Paint Damage

6: A Post ns
Rusted
Over 5mm



7: Door nsf
Dented
With Paint Damage

8: Sill ns
Dented
With Paint Damage




9: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint

10: B Post ns
Dented
With Paint Damage



11: Other
N/A
N/A

12: B Post os
Chipped
Multiple Chips



13: Door osf
Chipped
Multiple Chips

14: Sill os
Dented
Over 30% Of Panel



15: Wing of
Dented
Over 30mm

16: Wing of
Dented
With Paint Damage




17: Wing of
Scratched
Over 25mm Thru Paint

18: Fascia Panel
Broken
Replace



19: Seat Base Cover of
Soiled
Heavy

20: Seat Back Cover of
Soiled
Heavy



21: Seat Base Cover nsf
Soiled
Heavy

22: Fascia Panel
Soiled
Heavy

Interior

Carpet Condition OK
Seat Condition Poor

Upholstery Condition Poor
Odour No

Engine Runs Fault