



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

YK71KCZ

Mercedes-Benz Actros 2545

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details					
Reg. date	17/01/2022	VIN	W1T96342320551092	Axle Combi	6x2
Year	2022	Body Style	Tractor Unit	Steering Combi	Mid-Lift
Mileage	644,574 Km Warranted	MOT Due	30/11/2026	Rear Suspension	Air
Fuel Type	Diesel	Cab Type	STREAMSPACE CAB (2.5M, FLAT FLOOR)		
Colour	WHITE	Gearbox	AUTOMATIC		

SLIDING 5TH WHEEL, MIRROR CAMS

Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Air conditioning

Photos





Condition Check



Damage Photos



1: Wing of
Cracked
Replace



2: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



3: Wing nsf
Cracked
Replace

4: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



5: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm

6: Wing Front Arch Extension os
Scratched (Painted)
Over 25mm Thru Paint



7: Wing Front Arch Extension os
Scratched (Painted)
Over 25mm Thru Paint

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK