



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

YK71KHT

Mercedes-Benz Actros 2545

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present



Details					
Reg. date	17/01/2022	VIN	W1T96342320551094	Axle Combi	6x2
Year	2022	Body Style	Tractor Unit	Steering Combi	Mid-Lift
Mileage	579,290 Km Warranted	MOT Due	31/10/2026	Rear Suspension	Air
Fuel Type	Diesel	Cab Type	STREAMSPACE CAB (2.5M, FLAT FLOOR)		
Colour	WHITE	Gearbox	AUTOMATIC		

WARNING LIGHT ON DASH SLIDING 5TH WHEEL, MIRROR CAMS

Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: D Post os
Scratched
UpTo 25mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour -

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	OK	Service indicator light illuminated	OK