

VEHICLE INSPECTION REPORT

YK71KHR

Mercedes-Benz Actros 2545

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 17/01/2022

VIN W1T96342320551095

Axle Combi 6x2

Year 2022

Body Style Tractor Unit

Steering Combi Mid-Lift

Mileage 666,061 Km Warranted

MOT Due 30/06/2026

Rear Suspension Air

Fuel Type Diesel

Cab Type BIGSPACE CAB

Colour WHITE

Gearbox AUTOMATIC

SLIDING 5TH WHEEL, MIRROR CAMS

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3



OSO4

Features


- Air conditioning

Photos





Condition Check



Damage Photos



1: Wing osf
Missing
Replace



2: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm



3: Wing Front Arch Extension os
Scratched (Painted)
Over 25mm Thru Paint

4: Wing Front Arch Extension os
Scratched (Painted)
Over 25mm Thru Paint



5: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	