



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

LN67WND

Ford Transit 2.0 TDCi 130ps H2 Van

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow

Details					
Reg. date	30/09/2017	VIN	WF0XXXTTGXHB69881	CAP Below	£2,225.00
Year	2017	Body Style	Panel Van L3	Gearbox	MANUAL
Mileage	157,968 Miles Warranted	MOT Due	04/08/2026	Gears	6
Fuel Type	Diesel	CAP Clean	£3,600.00		
Colour	GREEN	CAP Average	£3,000.00		

OUTSTANDING RECALL, INPUT ERROR ON MOT HISTORY AD-BLUE


Tyres	
NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Bluetooth connection
- Drivers airbag
- Auxiliary input socket
- Passenger airbag
- Digital radio
- Central locking
- Front electric windows
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front Moulding
Missing
Replace



3: Door Moulding nsf
Scuffed (Unpainted)
UpTo 100mm

4: Qtr Panel nsr
Dented
Over 30mm



5: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm

6: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



7: Bumper Rear Moulding
Broken
Replace

8: Qtr Panel osr
Scratched
Over 25mm Thru Paint



9: Qtr Panel osr
Dented
With Paint Damage

10: Door osf
Chipped
Multiple Chips



11: Bumper Front
Scratched
25 to 100mm Thru Paint

12: Screen Front
Chipped
Over 10mm



13: Seat Base Cover osf
Holed
Over 3mm

14: Seat Base Cover nsf
Soiled
Heavy



15: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		