



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

BX14EVR

RENAULT MIDLUM 180 DXI

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Buyer To Apply


Details					
Reg. date	01/03/2014	Colour	WHITE	Cab Type	DAY CAB
Year	2014	VIN	VF644AGE000013349	Gearbox	MANUAL
Mileage	202,549 Km Not Warranted	Body Style	Skiploder	Axle Combi	4x2
Fuel Type	Diesel	MOT Due	30/04/2026	Rear Suspension	Steel

SHEETING SYSTEM, MHF BODY, EXTENDING ARM EQUIPMENT


Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Photos





Condition Check



Damage Photos



1: Bumper Front
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Bumper Front
 Scratched
 Over 25mm Not Thru Paint

4: Moulding nsf Wing
 Broken
 Replace

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK