



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**SP63GNU**

## Ford Transit T350 2.2 TDCi 125PS

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details					
Reg. date	13/11/2013	VIN	WF0NXXTTFNDB61885	CAP Clean	£2,550.00
Year	2013	Body Style	Tipper Double Cab	CAP Average	£1,950.00
Mileage	154,667 Miles Warranted	Service history	Yes	CAP Below	£1,325.00
Fuel Type	Diesel	Service documents	Printout	Gearbox	MANUAL
Colour	WHITE	MOT Due	Expired	Gears	6


\*WARNING LIGHT ON DASH\* TIPPER CONTROL REMOVED.

Tyres
NSF
NSR
OSF
OSR
Spare

## Features


- Radio/CD
- Front electric windows
- Central locking

## Photos






CYRB			e1×2007/46×0264		
0.53			×WFONXXTTFNDB61885×		
CP	B		3500		kg
G	R		5500		kg
A			1750		kg
6			2450		kg
W(mm)		L(mm)		a(mm)	
J 3954		FNC6			



## Condition Check



## Damage Photos



1: Carpets Front  
Torn  
Over 10mm



2: Seat Base Cover of  
Torn  
Over 3mm



3: Bonnet  
Dented  
With Paint Damage

4: Wing of  
Rusted  
Over 5mm



5: Door of  
Rusted  
Over 5mm

6: B Post of  
Dented  
Over 30mm



7: Qtr Panel of  
Dented  
With Paint Damage

8: Tailgate  
Rusted  
Over 5mm



9: Qtr Panel nsr  
Dented  
With Paint Damage

10: Sill ns  
Rusted  
UpTo 5mm



11: Door nsr  
Rusted  
Over 5mm

12: Door nsr  
Rusted  
Over 5mm



13: Door nsf  
Dented  
With Paint Damage

14: Wing nsf  
Rusted  
Over 5mm

**Interior**

<b>Carpet Condition</b>	Poor	<b>Upholstery Condition</b>	Poor
<b>Seat Condition</b>	Poor	<b>Odour</b>	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK