



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

LN67WNR

Ford Transit 350 2.0 TDCI 130PS

| Inspection | | Vehicle | |
|-----------------|----|---------|-----------|
| Serious Damage? | No | VAT | Plus VAT |
| | | V5 | To Follow |

Details

| | | | | | |
|-----------|----------------------------|-------------|-------------------|-----------|-----------|
| Reg. date | 30/09/2017 | VIN | WF0XXXTTGXHB70936 | CAP Below | £1,750.00 |
| Year | 2017 | Body Style | Panel Van L3 | Gearbox | MANUAL |
| Mileage | 198,657 Miles Warranted | MOT Due | 19/08/2026 | Gears | 6 |
| Fuel Type | Diesel | CAP Clean | £2,875.00 | | |
| Colour | GREEN | CAP Average | £2,400.00 | | |

COLLECTED AS NON-RUNNER AD-BLUE

Tyres



| |
|-------|
| NSF |
| NSR |
| OSF |
| OSR |
| Spare |

Features

- Front electric windows
- Central locking


Photos








Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5

2: Panel Front
Chipped
1 To 5



3: Panel Front
Scratched
UpTo 25mm Not Thru Paint

4: Door nsf
Dented
Hail - Moderate




5: Roof
Scratched
Over 25mm Thru Paint

6: Panel Rear
Dented
With Paint Damage



7: Panel Rear
Scratched
Over 25mm Thru Paint

8: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



9: Door osf
Chipped
Multiple Chips

10: Seat Base Cover osf
Soiled
Heavy



11: Seat Base Cover nsf
Soiled
Heavy

Interior

| Carpet Condition | Average | Upholstery Condition | Poor |
|--------------------------|---------|--|------|
| Seat Condition | Poor | Odour | Yes |
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Turbo Boosting | OK | Gearbox Static Gear Selection (engine running) | OK |
| Parking Brake | OK | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | DPF light illuminated | OK |
| ABS light illuminated | OK | Service indicator light illuminated | OK |