



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

LN67WVV

Ford Transit 350 2.0 TDCI 130PS

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow

Details					
Reg. date	30/09/2017	Colour	GREEN	CAP Average	£3,000.00
Year	2017	VIN	WF0XXTTGXHB76124	CAP Below	£2,225.00
Mileage	158,149 Miles Warranted	Body Style	Panel Van L3	Gearbox	MANUAL
Fuel Type	Diesel	CAP Clean	£3,600.00	Gears	6

OUTSTANDING RECALL, TURBO ISSUE AD-BLUE


Tyres	
NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Bluetooth connection
- Drivers airbag
- Auxiliary input socket
- Passenger airbag
- Digital radio
- Central locking
- Front electric windows
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint

2: Bonnet
Scratched
Over 25mm Thru Paint



3: Bonnet
Chipped
Multiple Chips

4: Roof
Chipped
Multiple Chips




5: Bumper Front
Scratched
Over 100mm Thru Paint

6: Wing Front Arch Extension ns
Scuffed (Unpainted)
UpTo 100mm



7: Door Mirror Glass ns
Missing
Replace

8: Door nsf
Scratched
Over 25mm Thru Paint



9: Qtr Panel nsr
Dented
Over 30mm

10: Qtr Panel nsr
Chipped
Multiple Chips



11: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

12: Qtr Panel nsr
Chipped
Multiple Chips



13: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm

14: Door osr
Dented
With Paint Damage



15: Door osr
Scratched
Over 25mm Thru Paint

16: Bumper Rear Moulding
Broken
Replace





17: Qtr Panel osr
Scratched
Over 25mm Thru Paint

18: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



19: Door osf
Chipped
Multiple Chips

20: Door Mirror Glass os
Missing
Replace



21: Seat Base Cover osf
Soiled
Heavy

22: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition

OK

Upholstery Condition

OK

Seat Condition

Poor

Odour

No

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		