



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

LN67WWO

Ford Transit 350 2.0 TDCI 130PS

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow

Details					
Reg. date	30/09/2017	VIN	WF0XXXTTGXHB76118	CAP Below	£2,975.00
Year	2017	Body Style	Panel Van L3	Gearbox	MANUAL
Mileage	112,596 Miles Warranted	MOT Due	27/08/2026	Gears	6
Fuel Type	Diesel	CAP Clean	£4,825.00		
Colour	GREEN	CAP Average	£4,025.00		

NON-RUNNER, STARTS & RUNS, NO CLUTCH, NOISY BACK AXLE, OUTSTANDING RECALL, WARNING LIGHTS ON DASH SIDE LOAD DOOR, TOW BAR


Tyres	
NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Bluetooth connection
- Drivers airbag
- Auxiliary input socket
- Passenger airbag
- Digital radio
- Central locking
- Front electric windows
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Qtr Panel nsr
Dented
With Paint Damage



3: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

4: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



5: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm

6: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



7: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm

8: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



9: Qtr Panel nsr
Dented
Over 30mm

10: Qtr Panel osr
Chipped
Multiple Chips



11: Qtr Panel osr
Dented
Over 30mm

12: Door osf
Chipped
Multiple Chips



13: Seat Base Cover nsf
Soiled
Heavy

14: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	Clutch Slip Test from Static	Fault
		No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	Fault		