



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

VU67HRZ

Dennis Elite 6

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Present

Details

Reg. date	05/10/2017	Colour	WHITE	Cab Type	CREW CAB
Year	2017	VIN	SEG2628JR6BH23783	Gearbox	AUTOMATIC
Mileage	53,600 Km Warranted	Body Style	Refuse Collector	Axle Combi	6x4
Fuel Type	Diesel	MOT Due	30/09/2026	Rear Suspension	Steel

OLTP 22 BODY (YEAR 2017)

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Park assist camera


Photos







Condition Check



Damage Photos



1: Wing of
Scratched
Up To 25mm Thru Paint



2: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



3: Bonnet
Scratched
Over 25mm Not Thru Paint

4: Wing nsf
Cracked
Replace



5: Door Mirror Assy nsf
Broken
Replace

6: Seat Base Cover nsf
Holed
Over 3mm



7: Wing Front Arch Extension ns
Scratched (Painted)
Over 25mm Not Thru Paint

8: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



9: Seat Base Cover of
 Holed
 Over 3mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK