



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**VU67HRW**

## Dennis Elite 6

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT  
V5 Present

### Details

Reg. date	20/09/2017	Colour	WHITE	Cab Type	CREW CAB
Year	2017	VIN	SEG2628JR6BH23781	Axle Combi	6x4
Mileage	76,367 Km Warranted	Body Style	Refuse Collector	Rear Suspension	Steel
Fuel Type	Diesel	MOT Due	31/08/2026		

OLTP 22 BODY (YEAR 2017)

### Tyres






NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

## Features

- Park assist camera


## Photos







## Condition Check



## Damage Photos



1: Door Mirror Assy  
Scuffed (Unpainted)  
Over 100mm




2: Bumper Front Moulding  
Scuffed (Unpainted)  
Over 100mm



3: Bumper Front Moulding  
Scuffed (Unpainted)  
Over 100mm

4: Door Mirror Assy nsf  
Broken  
Replace



5: Wing Front Arch Extension os  
Scratched (Painted)  
Up To 25mm Not Thru Paint

6: Door osf  
Scratched  
Over 25mm Not Thru Paint



7: Seat Base Cover osf  
Holed  
Over 3mm

## Interior

<b>Carpet Condition</b>	Average	<b>Upholstery Condition</b>	Average
<b>Seat Condition</b>	Average	<b>Odour</b>	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK