



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

YA24HSZ

Iveco Daily 35-140

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Present

Details

Reg. date	01/07/2024	VIN	ZCFCL35A605602047	CAP Below	£11,150.00
Year	2024	Body Style	Panel Van	Gearbox	MANUAL
Mileage	59,684 Miles TBC	Service history	Yes	Gears	6
Fuel Type	Diesel	CAP Clean	£13,450.00		
Colour	WHITE	CAP Average	£12,700.00		

AD-BLUE, E/ MIRRORS, 4100 WB

Tyres


NSF
NSR
OSF
OSR
Spare

Features

- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Cruise control
- Drivers airbag
- Digital radio
- Passenger airbag
- Air conditioning
- Central locking


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Panel Front
Chipped
Multiple Chips



3: Qtr Panel nsr
Dented
With Paint Damage

4: Qtr Panel nsr
Dented
With Paint Damage




5: Qtr Panel Moulding ns
Broken
Replace

6: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



7: Door nsr
Dented
Over 30mm

8: Door osr
Dented
Over 30mm



9: Qtr Panel osr
Dented
With Paint Damage

10: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



11: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm

12: Seat Base Cover osf
Soiled
Heavy



13: Seat Base Cover nsf
Soiled
Heavy

14: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition
Seat Condition

OK
Poor

Upholstery Condition
Odour

OK
No

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		