



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

YC20SSX

Ford Transit Connect 240 1.5 ECOBLUE 100PS

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow

Details					
Reg. date	25/03/2020	VIN	WF0SXXWPGSLB89619	CAP Below	£4,550.00
Year	2020	Body Style	Panel Van	Gearbox	MANUAL
Mileage	58,015 Miles Warranted	MOT Due	30/03/2026	Gears	6
Fuel Type	Diesel	CAP Clean	£6,475.00		
Colour	WHITE	CAP Average	£5,700.00		

OIL LEAK AD-BLUE, TWIN LOADING DOORS, E/MIRRORS



Tyres
NSF
NSR
OSF
OSR
Spare

Features


- Front parking sensor
- Front electric windows
- Park assist camera
- Rear parking sensor
- Air conditioning

Photos





Condition Check




Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

2: Bonnet
Chipped
Multiple Chips



3: Screen Front
Chipped
Up To 10mm

4: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



5: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

6: Door nsr
Scratched
Over 25mm Thru Paint



7: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm

8: Carpets Front
Holed
Over 3mm

Interior

Carpet Condition	Average	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK