



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**PE65VDJ**

## Daf LF 150

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

### Details

Reg. date	29/10/2015	VIN	XLRAEL1500L448562	Gearbox	MANUAL
Year	2015	Body Style	Box Van	Axle Combi	4x2
Mileage	569,893 Km Warranted	Service history	Yes	Rear Suspension	Steel
Fuel Type	Diesel	MOT Due	30/09/2026	Tail Lift	Cantilever
Colour	RED	Cab Type	DAY CAB		



\*COLLECTED AS NON-RUNNER, EML\*

### Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

### Photos





## Condition Check



## Damage Photos



1: Wing of  
Scratched  
Over 25mm Thru Paint

2: Bumper Front  
Scratched  
25 to 100mm Thru Paint



3: Screen Front  
Chipped  
UpTo 10mm

4: Grille Front  
Broken  
Replace



5: Bumper Front  
Scratched  
25 to 100mm Thru Paint

6: Wing nsf  
Scratched  
UpTo 25mm Not Thru Paint



7: Door Mirror Assy nsf  
Scuffed (Unpainted)  
Over 100mm

8: Wing Front Arch Extension ns  
Scratched (Painted)  
Over 25mm Thru Paint



9: Bumper Rear  
Rusted  
Over 5mm

10: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



11: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint

12: Door osf  
Chipped  
Edge Chip



13: Door Mirror Assy osf  
Scuffed (Unpainted)  
Over 100mm

14: Wing osf  
Scratched  
Over 25mm Thru Paint



15: Door osf  
 Scratched  
 Over 25mm Not Thru Paint

16: Carpets Front  
 Holed  
 Over 3mm



17: Switches And Controls  
 Broken  
 Replace

**Interior**

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK