



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

SG640LN

MITSUBISHI L200 DI-D 4 LIFE

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details					
Reg. date	16/10/2014	VIN	MMCENKB40FD821965	CAP Below	£2,225.00
Year	2014	Body Style	Pickup Single Cab	Gearbox	MANUAL
Mileage	61,838 Miles Warranted	MOT Due	20/10/2026	Gears	5
Fuel Type	Diesel	CAP Clean	£4,075.00	Axle Combi	4x4
Colour	BLACK	CAP Average	£3,250.00		

WARNING LIGHTS ON DASH

Tyres
NSF
NSR
OSF
OSR
Spare

Features

- Front electric windows
- Central locking


Photos








Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bonnet
Chipped
Edge Chip



3: Moulding nsf Wing
Scratched (Painted)
Over 25mm Thru Paint

4: Panel Rear
Chipped
Multiple Chips



5: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

6: Boot Lid
Scratched
Up To 25mm Not Thru Paint



7: Door Moulding osf
Scratched (Painted)
Over 25mm Thru Paint

8: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



9: Moulding nsf Wing
 Scratched (Painted)
 Over 25mm Not Thru Paint

10: Carpets Front
 Torn
 Over 10mm



11: Seat Base Cover nsf
 Torn
 Over 3mm

12: Carpets Front
 Torn
 Over 10mm

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	Poor	Odour	Yes
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
Airbag light illuminated	OK	Oil warning light illuminated	OK
ABS light illuminated	Fault	DPF light illuminated	OK
		Service indicator light illuminated	OK