

VEHICLE INSPECTION REPORT

LT68GBZ

MERCEDES-BENZ AROCS 3240

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 08/11/2018

Colour WHITE

Cab Type DAY CAB

Year 2018

VIN WDB96423020237406

Gearbox AUTOMATIC

Mileage 206,863 Km Warranted

Body Style Tipper

Axle Combi 8x4

Fuel Type Diesel

MOT Due Expired

Rear Suspension Steel

BEEN STOOD A WHILE, COLLECTION FROM PRESTON PALFINGER EPSILON M125L CRANE (YEAR 2018), SHEETING SYSTEM, MID-STEER

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3



OSO4

Features

- Bluetooth connection
- Air conditioning
- Cruise control
- Front electric windows
- Park assist camera
- Central locking
- Radio/CD
- Cloth seat trim

Photos










Condition Check



Damage Photos



1: Bumper Front
Poor Previous Repair
Poor Paint

2: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



3: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		