



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**CN65SYY**

## Mercedes-Benz Atego 816

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

### Details

Reg. date	17/09/2015	VIN	WDB9670022L972578	Axle Combi	4x2
Year	2015	Body Style	Curtainside	Rear Suspension	Steel
Mileage	725,338 Km Not Warranted	MOT Due	31/05/2026	Rear Doors	Barn
Fuel Type	Diesel	Cab Type	DAY CAB		
Colour	WHITE	Gearbox	AUTOMATIC		

### Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

## Features

- Bluetooth connection
- Radio/CD
- Passenger airbag
- Cruise control
- LED headlights
- Central locking
- Auxiliary input socket
- Front electric windows
- Cloth seat trim
- Digital radio
- Drivers airbag


## Photos







## Condition Check



## Damage Photos



1: Moulding of Wing  
Scuffed (Unpainted)  
Up To 100mm

2: Door of  
Chipped  
Edge Chip



3: Door osf  
Dented  
Over 30mm

4: Door nsf  
Scratched  
UpTo 25mm Thru Paint



5: Door nsf  
Chipped  
Over 5mm

6: Screen Front  
Cracked  
Replace

**Interior**

Carpet Condition	OK	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK

Windows

OK

Radio

OK

Steering

OK