

# VEHICLE INSPECTION REPORT

**PF66WLV**

## Iveco Daily 35-140 2.3 3450WB

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date 20/12/2016

Year 2016

Mileage 184,179 Miles  
Warranted

Fuel Type Diesel

Colour WHITE/GREEN

VIN ZCFCD35A505124653

Body Style Dropside MWB

MOT Due 04/11/2025

CAP Clean £3,550.00

CAP Average £2,925.00

CAP Below £2,225.00

Gearbox MANUAL

Gears 6

Axle Combi 4x2

Tail Lift Column

COLUMN TAIL LIFT, E/WINDOWS

### Tyres

NSF

NSR

OSF

OSR

Spare


### Photos







## Condition Check



## Damage Photos



1: Wing osf  
Dented  
With Paint Damage



2: Bonnet  
Chipped  
Multiple Chips



3: Bumper Front Moulding  
Scratched (Painted)  
Over 25mm Thru Paint



4: Wing nsf  
Scratched  
Over 25mm Thru Paint



5: Door nsf  
Scratched  
Over 25mm Thru Paint



6: Door osf  
Scratched  
Over 25mm Thru Paint



7: Door osf  
Dented  
With Paint Damage



8: Carpets Front  
Holed  
Over 3mm





9: Seat Base Cover osf  
Holed  
Over 3mm

10: General Interior  
Soiled  
Light



11: General Interior  
Soiled  
Light

12: Other  
N/A  
N/A

## Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK