



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

BX06KXM

Daf LF 45.140

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present




Details			
Reg. date	17/03/2006	VIN	XLRAE45BF0L315519
Year	2006	Body Style	Access Platform
Mileage	313,650 Km Warranted	Service history	Yes
Fuel Type	Diesel	MOT Due	30/09/2026
Colour	WHITE	Cab Type	DAY CAB
		Gearbox	MANUAL
		Axle Combi	4x2
		Rear Suspension	Steel

CONTROL SWITCH NOT WORKING FOR HOIST, 2 WAY INTERCOM DOESN'T WORK VERSALIFT EUROTEL 29NE PLATFORM

Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


Photos







Condition Check



Damage Photos



1: Wing of
Scratched
Over 25mm Not Thru Paint

2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Bonnet
Chipped
Multiple Chips

4: Bumper Front
Scratched
25 to 100mm Thru Paint



5: Fog Lamp Surround ns
Scratched (Painted)
Over 25mm Thru Paint

6: Wing nsf
Scratched
Over 25mm Thru Paint



7: Wing Front Arch Extension ns
Broken
Replace

8: Door nsf
Scratched
Over 25mm Thru Paint



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

10: Qtr Panel osr
Scratched
Over 25mm Thru Paint



11: Wing Front Arch Extension os
Scratched (Painted)
Over 25mm Thru Paint

12: Door osf
Chipped
Edge Chip



13: Seat Base Cover nsf
Holed
Over 3mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK